## ANNEX 2




## Vehicle Technical Inspection Form Nissan Navara 2.5 TD EUMM 076



Technical Specifications		Technical status	
Brand	Nissan	Engine	Satisfactory works
Model	Navara	Suspension	Good
	2.5 TD	Brakes	Work
Market	EUROPE	Batteries	Good
Build date	2011	Fuel system	Works
Engine	YD25DDTi	Hand brake	Good
model			
Transmission	MTM, 6 speed	Footbrake	Works
Engine No.		Lighting	Works
Vin No.	VSKBVAD40U0433355	Transmission	Satisfactory works
Mileage	110 546 km	Tires	Good
Color	Blue	Run flat system	


The vehicle is in reasonable shape and corresponds to the service life of thirteen years.

- Vehicle has been used on roads and hard terrain in mountains for logistic operations
- Vehicle has been serviced after each 10 000 km. Last service on 16.12.2022 at 102000Km
- Accidents and maintenance history below









Veh: 2011 NISSAN Navara 2.5 TD YD25DDTi Diesel VIN: VSKBVAD40U0433355 Odometer: 110118 Dept: Transport Section Driver: KARUMIDZE Lado L-0199 [16/09/.

Order No	Date	Status	Odometer	Serviced By	
EU-102	2015-10-13	Completed	29,062	IBERIA TECH AUTOMOTIVE LTD	
Summary: Tire work Wheel alignment four points Full Desc: Tires rotation					
EU-222	2015-11-26	Completed	52,945	IBERIA TECH AUTOMOTIVE LTD	
Summary: Supply Full Desc: Battery 12v 74 Ah					
EU-678	2016-05-17	Completed	55,278	IBERIA TECH AUTOMOTIVE LTD	
Summary: Servi Full Desc:	ce Service A				
EU-695	2016-05-23	Completed	55,278	EUMM	
Summary: Electric Repair Full Desc: AC Freon added.					
EU-820	2016-07-05	Completed	57,420	IBERIA TECH AUTOMOTIVE LTD	
Summary: Mechanical Repair Full Desc: Supply rear brake pads					
EU-840	2016-07-08	Completed	57,420	EUMM	
Summary: Mechanical Repair Full Desc: Rear brake pads were fixed.					
EU-1770	2017-06-19	Completed	70,040	IBERIA TECH AUTOMOTIVE LTD	
Summary: Service Service B Full Desc: Supply only parts and fluid					
EU-1792	2017-06-28	Completed	70,699	EUMM	
•····· • ·	0 · D				

Summary: Damage Repair Body damage repair Full Desc: The back part of the vehicle is damaged EU-4349 2019-10-14 Completed 92.495 **TEGETA MOTORS** Summary: Service Service B Full Desc: Completed EU-4479 2019-11-12 92,971 **TEGETA MOTORS** Summary: Electric Repair Supply Battery Full Desc: EU-5111 2020-07-09 Completed 94,230 EUMM Summary: Check/Charge A/C Full Desc: Saloon filter was cleaned EU-5548 2021-04-21 Completed 97,000 **TEGETA MOTORS** Summary: Service Service A Full Desc: EU-5635 2021-07-20 Completed 96,925 **TEGETA MOTORS** Summary: Electric Repair El.Diagnostic Full Desc: Check light on Dashboard, loose the power while driving EU-5704 2021-09-08 98,135 Pending JSC INSURANCE COMPANY ALDAGI (LEGAL SUCCESSOR OF "ALDAGI BCI") Summary: Damage Repair Body damage repair Full Desc: The rear end of the vehicle is damaged EU-6116 2022-05-16 Completed 98,000 Summary: Full Desc: EU-7223 2023-11-10 Completed 108,098 **TEGETA MOTORS** name Electric Densis Coursely Dett