


Vehicle Technical Inspection Form Nissan Navara 2.5 TD EUMM 116



Technical Specifications		Technical status	
Brand	Nissan	Engine	Satisfactory works
Model	Navara	Suspension	Good
	2.5 TD	Brakes	Work
Market	EUROPE	Batteries	Good
Build date	2011	Fuel system	Works
Engine	YD25DDTi	Hand brake	Good
model			
Transmission	MTM, 6 speed	Footbrake	Works
Engine No.		Lighting	Works
Vin No.	VSKBVAD40U0433912	Transmission	Satisfactory works
Mileage	86 903 km	Tires	Good
Color	Blue	Run flat system	

- The vehicle is in reasonable shape and corresponds to the service life of thirteen years.
- Vehicle has been used on roads and hard terrain in mountains for logistic operations
- Vehicle has been serviced after each 10 000 km. Last service on 17.11.2022 at 76 000 KM;

Accidents and maintenance history below
















Veh. No: EUMM 116

Veh: 2011 NISSAN Navara 2.5 TD YD25DDTi Diesel

VIN: VSKBVAD40U0433912

Summary: Damage Repair

Full Desc: repair winch controller box(Plastic cover)

Odometer: 86617

Loc: TBILISI

Dept: Transport Section

Driver: KARUMIDZE Lado L-0199 [16/09/2019 - 1

Order No	Date	Status	Odometer	Serviced By		
EU-24	2015-08-19	Completed	36,522	IBERIA TECH AUTOMOTIVE LTD		
Summary: Tire work Wheel alignment four points Full Desc:						
EU-173	2015-10-30	Completed	36,522	IBERIA TECH AUTOMOTIVE LTD		
Summary: Damage Repair Body damage repair Full Desc: Reference# 7/003/EUMM-13-3016 The front bumper was damaged						
EU-232	2015-11-30	Completed	36,522	IBERIA TECH AUTOMOTIVE LTD		
Summary: Tire work Tire replacement & wheel balance Full Desc:						
EU-330	2015-12-30	Completed	39,363	IBERIA TECH AUTOMOTIVE LTD		
Summary: Tire work Tire replacement & wheel balance Full Desc: Rear Axle						
EU-800	2016-06-29	Pending	39,363	INSURANCE COMPANY UNISON		
Summary: Damage Repair Body damage repair Full Desc: The rear left lamp is broken						
EU-965	2016-08-25	Completed	42,300	IBERIA TECH AUTOMOTIVE LTD		
Summary: Service Service A Full Desc:						
EU-1132	2016-10-13	Pending	42,407	INSURANCE COMPANY UNISON		
Summary: Damage Repair Body damage repair Full Desc: The front part of EUMM 116 was damaged						
EU-1353	2017-01-13	Completed	42,407	EUMM		

Full Desc: We need the trailer socket and plug 2019-07-23 FU-4067 65,946 **FUMM** Completed Summary: Damage Repair Full Desc: Front RH mudguard EU-4201 2019-08-22 EUMM Completed 66,815 Summary: Electric Repair Full Desc: Windscreen washer motor EU-4400 2019-10-18 Completed 68,071 Summary: Service Periodical Technical Inspection Full Desc: 2020-06-22 Completed 71,696 **EUMM** Summary: Other Head lights polishing Full Desc: EU-5296 2020-09-28 72.340 INSURANCE COMPANY UNISON Pending Summary: Damage Repair Body damage repair Full Desc: Cracks on the right hand side of the front wheel arch 2020-10-07 **EUMM** Completed 72,400 Summary: Service Brake hydraulic fluid drain/refill Full Desc: Change rear brake shoe pads, bleed the brake system EU-5324 2020-10-09 Completed 72,400 **EUMM** Summary: Electric Repair Change battery Full Desc: swap battery from EUMM 037(write of case) 2021-10-05 Completed 74,300 Summary: Service Periodical Technical Inspection Full Desc: EU-5796 2021-11-17 Completed 74,780 **EUMM** Summary: Service Service A Full Desc: EU-6619 2023-01-11 82,729 JSC INSURANCE COMPANY ALDAGI Pending (LEGAL SUCCESSOR OF "ALDAGLECI")