



Vehicle Technical Inspection Form
Nissan Navara 2.5 TD
EUMM 078



Technical Specifications		Technical status	
Brand	Nissan	Engine	Satisfactory works
Model	Navara	Suspension	Good
	2.5 TD	Brakes	Work
Market	EUROPE	Batteries	Good
Build date	2011	Fuel system	Works
Engine model	YD2DDTi	Hand brake	Good
Transmission	MTM, 6 speed	Footbrake	Works
Engine No.		Lighting	Works
Vin No.	VSKBVAD40U0433660	Transmission	Satisfactory works
Mileage	111 605 km	Tires	Good
Color	Blue	Run flat system	

- The vehicle is in reasonable shape and corresponds to the service life of thirteen years.
- Vehicle has been used on roads and hard terrain in mountains for logistic operations
- Vehicle has been serviced after each 10 000 km. Last service on 16.11.2022 at 103 000 KM;

The accidents history and maintenance records below.





Work Order History and Cost by Vehicle No

Veh. No: EUMM 078

Veh: 2011 NISSAN Navara 2.5 TD YD25DDTi Diesel

VIN: VSKBVAD40U0433660

Odometer: 111111

Loc: GORI

Dept: Transport Section

Driver: KARUMIDZE Lado L-0199 [16/09/2019 - 14/12/20;

Order No	Date	Status	Odometer	Serviced By	Total
EU-140	2015-10-21	Completed	59,000	IBERIA TECH AUTOMOTIVE LTD	
Summary: Electric Repair El.Diagnostic					
Full Desc: Check engine on dash board,Engine loose the power					
EU-512	2016-03-01	Completed	60,980	IBERIA TECH AUTOMOTIVE LTD	
Summary: Electric Repair Change battery					
Full Desc: Battery needs to be changed 12V 70 Ah					
EU-767	2016-06-15	Completed	63,513	IBERIA TECH AUTOMOTIVE LTD	
Summary: Service Service A					
Full Desc:					
EU-1102	2015-06-11	Completed	55,840	IBERIA TECH AUTOMOTIVE LTD	
Summary: Service Brake hydraulic fluid drain/refill					
Full Desc:					
EU-1489	2017-03-13	Pending	68,837	INSURANCE COMPANY UNISON	
Summary: Damage Repair Body damage repair					

Full Desc: The rear door and fender is damaged

EU-1583 2017-04-14 Completed 68,837 EUMM

Summary: Mechanical Repair

Full Desc: turbine hose was fixed

EU-2149 2017-11-02 Pending 75,353 IBERIA TECH AUTOMOTIVE LTD

Summary: Electric Repair

Full Desc: Charging system needs to checked

EU-2443 2018-02-23 Completed 78,160 IBERIA TECH AUTOMOTIVE LTD

Summary: Service Service B

Full Desc: Filters from EUMM Stock,check brake's

EU-2673 2018-06-29 Completed 79,950 TEGETA MOTORS

Summary: Electric Repair El.Diagnostic

Full Desc: el. problem.power supply to the starter

EU-2750 2018-07-04 Completed 80,324 TEGETA MOTORS

Summary: Electric Repair

Full Desc: Check A/C,doesn't blow the cold air

EU-4182 2019-08-16 Pending 87,301
ALDAGI BCI JSC (REPLACED WITH
LEGAL SUCCESSOR "JSC INSURANCE
COMPANY ALDAGI")

Summary: Damage Repair Body damage repair

Full Desc: Scratches on the front bumper; small dents on the hood; Damage to the rear right mudguard

EU-4243 2019-09-09 Completed 88,206 TEGETA MOTORS

Full Desc: the hood latch was adjusted

EU-5332 2020-10-13 Pending 95,005 TEGETA MOTORS

Summary: Electric Repair Supply Battery

Full Desc:

EU-6442 2022-11-16 Completed 103,540 TEGETA MOTORS

Summary: Service Service B

Full Desc:

EU-6460 2022-11-15 Completed 102,200

Summary:

Full Desc:

EU-7412 2024-01-25 Completed 109,554 TEGETA MOTORS

Summary: Tire work Tire replacement & wheel balance

Full Desc: Winter tires

EU-7553 2024-03-28 Completed 110,195 TEGETA MOTORS

Summary: Electric Repair Supply Battery

Full Desc:

EU-7602 2024-04-18 Completed 110,195 TEGETA MOTORS

Summary: Mechanical Repair Change FR Brake pads

Full Desc:

EU-7621 2024-05-01 Pending 110,590 TEGETA MOTORS

Summary: Electric Repair

Full Desc: Check engine light is on

1 2 3 4

1 2 3 4